Energy Source Evaluation

Equipment Model/Name:	Quick Mold Change Device
Evaluated By:	Duane Rondeau
Evaluation Date:	2 June 2004

Definitions:

- Energy Source Type: Mechanical (Gravity, Springs, Hydraulic, Pneumatic), Electrical, Thermal, Chemical, Etc.
- Component Name: Bar Conveyor Drive, Depalleter pusher lift, FDC Drive, etc.
- Recommended Isolation: Electrical disconnect, block/chain, pneumatic/hydraulic disconnect, discharge, etc.

Energy Source Type	Component Name	Recommended Isolation
Electrical	Gearmotors	Lockout disconnect on electrical panel
Electrical	Electrical Panel and Wiring	Lockout disconnect on electrical panel
Gravity	Loader/Unloader Elevator	Block and/or chain carriage in up position